

## TIE BOLT HOLE REPAIR SYSTEM

Patching and waterproofing tie bolt holes has never been easier than with the Flupp 22ST and M P&P Mortar repair system.

The Tie Bolt Hole repair system is recommended for insitu concrete structures such as:

- Lift pits
- Sewage and Water Treatment Plants
- Basement Retaining Walls
- Bund Walls
- Swimming Pools
- Water Tanks



Flupp 22ST is a non-rigid PVC internal water seal for spacer tubes, where the internal diameter is 22mm, and is resistant to:


- Saline Solutions
- Diluted Alkaline Solutions
- Soap Suds

- Ammonia Water
- Tested to 4.5 bar pressure

**M P&P Mortar** is a fast setting non-shrink mortar, containing Xypex Crystalline Technology, for concrete repairs where waterproofing is a requirement.

M P&P Mortar has many advantages including:

- Non-Toxic
- Non-Metallic (won't rust or deteriorate) AS/NZS 4020:2005 Compliant
- Single component (simply add water)
- Excellent Structural Strength



Application schematic and photos illustrating use of the repair system.









Xypex Australia has a network of offices and distributors located throughout Australia and New Zealand. To locate your nearest supplier, visit www.xypex.com.au

